

Message

From: STILZ, DON [DSTILZ@idem.IN.gov]
Sent: 8/9/2018 6:35:58 PM
To: Bury, Carolyn [bury.carolyn@epa.gov]; Neal, Conor [Neal.Conor@epa.gov]; Sundar, Bhooma [sundar.bhooma@epa.gov]; Brad Gentry (bgentry@iwmconsult.com) [bgentry@iwmconsult.com]
Subject: RE: Franklin Street Department
Attachments: 68291857.pdf

All the information should be in the report, dated May 30, 2013, I sent you a couple of days ago, but it's attached here for Brad's benefit. I have not looked at very much of the report, but what I have seen looks like the street department's consultant is attributing the TCE it detected to Amphenol (see page 12 of 180).

From: Bury, Carolyn [mailto:bury.carolyn@epa.gov]
Sent: Thursday, August 09, 2018 1:27 PM
To: STILZ, DON <DSTILZ@idem.IN.gov>; Neal, Conor <Neal.Conor@epa.gov>; Sundar, Bhooma <sundar.bhooma@epa.gov>; Brad Gentry (bgentry@iwmconsult.com) <bgentry@iwmconsult.com>
Subject: RE: Franklin Street Department

Thanks.

When you get a chance, we would like more details about the release and the extent of plume migration.

From: STILZ, DON [mailto:DSTILZ@idem.IN.gov]
Sent: Thursday, August 09, 2018 7:59 AM
To: Bury, Carolyn <bury.carolyn@epa.gov>; Neal, Conor <Neal.Conor@epa.gov>; Sundar, Bhooma <sundar.bhooma@epa.gov>; Brad Gentry (bgentry@iwmconsult.com) <bgentry@iwmconsult.com>
Subject: Franklin Street Department

I need to clarify a statement I passed along yesterday. The street department site, which is located southwest of Amphenol, was the location of a LUST cleanup that had 19 ppb of TCE in the groundwater. PCE was not found there.